



Flat Rate Repair Pricing

Best Service, Best Price

All repairs carry a standard 6-month warranty
 Questions, call 801-546-4146 x 4 or 1-800-498-5795 x 4

Submit repairs online at NextATM.com/repairs

HYOSUNG			
Part Type	Repair code	Repair	Price
Dispensers	REP-00014	1,000 Note Dispenser Complete Refurbishment	\$239
	REP-00015	2,000 Note Dispenser Complete Refurbishment	\$239
	REP-00040	4,000 Note Dispenser Complete Refurbishment	\$299
	REP-00041	6-8,000 Note Dispenser Complete Refurbishment	\$325
	REP-00016	Drawer Style Dispenser Complete Refurbishment	\$259
	REP-00055	Dispenser Board Complete Refurbishment	\$125
PRICE DOES NOT INCLUDE DISPENSER BOARD REPAIR IF NEEDED. ADDITIONAL CHARGE OF \$100 FOR EXTENSIVE OR RODENT DAMAGE. AN ADDITIONAL \$65 CHARGE WILL BE ADDED FOR UPGRADING DISPENSERS TO 6K OR 8K SIZE			
Cassettes	REP-00021	1,000 Note Cassette Complete Refurbishment	\$175
	REP-00022	2,000 Note Cassette Complete Refurbishment	\$175
ADDITIONAL CHARGE OF \$100 FOR EXTENSIVE OR RODENT DAMAGE			
Keypads	REP-00050	5000K and 6000K Keypads Complete Refurbishment	\$189
	REP-00104	PCI 3.0/8000R Keypads Complete Refurbishment	\$235
	REP-00106	Repair 3.0 Keypad Exchange	\$325
Mainboards & Electronics	REP-00025	Mainboard Reprogram	\$115
	REP-00026	Mainboard Extensive Component Repair	\$165
Printers	REP-00038	Hyosung/Hantle (Tranax) Printer (All Models) Complete Refurbishment	\$239
	REP-00057	Hyosung/Hantle (Tranax) Printer Board Complete Refurbishment	\$125
	REP-00101	1500SE EMV Firmware Upgrade	\$75
PRICE DOES NOT INCLUDE BOARD OR CUTTER ASSEMBLY			
LCDs	REP-00027	LCD 5.7" & 10.4" Complete Refurbishment	\$149
	REP-00071	LED Upgrade	\$179
Power Supply	REP-00028	Power Supply Complete Refurbishment	\$189
Card Reader	REP-00103	EMV Card Reader Complete Refurbishment	\$189
ATM Service	REP-00108	Service Charge for Full ATM Clean and Refurbishment	\$75



Part Type	Repair code	Repair Service	Price
Dispensers	REP-00017	TCDU Dispenser Complete Refurbishment	\$249
	REP-00054	SCDU Dispenser Complete Refurbishment	\$249
	REP-00018	MCDU/RCDU/HCDU Single Cassette Dispenser Complete Refurbishment	\$249
	REP-00019	MCDU/SCDU Multiple Cassette Dispenser Complete Refurbishment	\$379
	REP-00055	Dispenser Board Repair Complete Refurbishment	\$125
	REP-00073	WCDU Dispenser Complete Refurbishment	\$349
	REP-00107	PCDU Dispenser Complete Refurbishment	\$499
	PRICE DOES NOT INCLUDE DISPENSER BOARD REPAIR IF NEEDED. ADDITIONAL CHARGE OF \$100 FOR EXTENSIVE OR RODENT DAMAGE. AN ADDITIONAL \$65 CHARGE WILL BE ADDED FOR UPGRADING DISPENSERS TO 6K OR 8K SIZE.		
Cassettes	REP-00023	Cassette (All Models) Complete Refurbishment	\$149
	ADDITIONAL CHARGE OF \$100 FOR EXTENSIVE OR RODENT DAMAGE		
Mainboards & Electronics	REP-00066	Mainboard Software Upgrade	\$115
	REP-00067	Mainboard Extensive Component Repair	\$165
Keypads	REP-00050	Complete Refurbishment	\$189
Printers	REP-00038	Printer (All Models) Complete Refurbishment	\$239
	REP-00057	Printer Board Complete Refurbishment	\$125
	PRICE DOES NOT INCLUDE BOARD OR CUTTER ASSEMBLY		
Power Supply	REP-00028	Power Supply Complete Refurbishment	\$189
ATM Service	REP-00108	Service Charge for Full ATM Clean and Refurbishment	\$75



Dispensers	REP-00029	De La Rue SDD Dispenser Complete Refurbishment INCLUDES METAL RAILS AND METAL TIMING WHEEL COVER	\$239
	REP-00030	De La Rue Mini Mech Dispenser Complete Refurbishment	\$219
	REP-00033	De La Rue Dispenser Board Repair if Needed	\$150
	PRICE DOES NOT INCLUDE DISPENSER BOARD REPAIR IF NEEDED. ADDITIONAL CHARGE OF \$100 FOR EXTENSIVE OR RODENT DAMAGE		
Cassettes	REP-00034	De La Rue SDD Cassette Complete Refurbishment INCLUDES METAL RAILS	\$139
	ADDITIONAL CHARGE OF \$100 FOR EXTENSIVE OR RODENT DAMAGE		